

| ATA Ref  | TYPE | Description   | Partnumber  | ISSUE      | REV | A/C     |
|----------|------|---|---|------------|-----|---------|
| 26-20-10 | ACMM | Pressure Reducer, HALON                                 | D41428<br>D41552<br>E62691-00   | 01.10.2008 | 2   | Airbus  |
| 35-10-25 | CMM  | Protective Breathing Equipment OXYCREW                  | E28180-SERIES   | 14.07.2008 | 4   | ALL     |
| 35-20-10 | CMM  | Passenger Service Unit Panel Assembly                   | E740-SEERIES  | 01.04.2003 | 1   | Boeing  |
| 35-20-20 | CMM  | Emergency Oxygen Container Assembly (FWD)               | E75010-SERIES   | 21.01.2005 | 2   | Boeing  |
| 35-20-30 | CMM  | Emergency Oxygen Container Assembly (AFT/LAV)           | E75020/E75030-SERIES  | 01.11.1999 | 0   | Boeing  |
| 35-21-10 | CMM  | Passenger Emergency Oxygen Container Assembly Type I    | 12C15_0000/0003-SERIES<br>13C15_0000/0003-SERIES<br>14C15_0000/0003-SERIES          | 01.05.1999 | 1   | Airbus  |
| 35-21-11 | CMM  | Passenger Emergency Oxygen Container Assembly 28V Latch | 12C15_1000-SERIES<br>13C15_1000-SERIES<br>14C15_1000-SERIES                         | 01.03.2000 | 0   | Tupolev |
| 35-21-12 | CMM  | Passenger Emergency Oxygen Container Assembly Type I    | 12C15/22-0004/0005-SERIES<br>13C15/22-0004/0005-SERIES<br>14C15/22-0004/0005-SERIES | 01.07.2008 | 3   | Airbus  |
| 35-21-13 | CMM  | Passenger Emergency Oxygen Container Assembly Type V    | 52C15/22-0005/0006 Series<br>53C15/22-0005/0006 Series<br>54C15/22-0005/0006 Series | 01.01.2009 | 2   | Airbus  |
| 35-21-14 | CMM  | Passenger Emergency Oxygen Container Assembly Type VI   | 62C15/22-0005/0006 Series<br>63C15/22-0005/0006 Series<br>64C15/22-0005/0006 Series | 01.01.2009 | 2   | Airbus  |

| ATA Ref  | TYPE | Description  | Partnumber  | ISSUE      | REV | A/C     |
|----------|------|--|---|------------|-----|---------|
| 35-21-20 | CMM  | Passenger Emergency Oxygen Container Assembly Type II      | 22C15_0000-SERIES   | 01.03.1992 | 0   | Airbus  |
| 35-21-21 | CMM  | Passenger Emergency Oxygen Container 28V, Blinker Mask     | 22C12_2000-SERIES   | 01.07.2006 | 1   | LH-B737 |
| 35-21-30 | CMM  | Passenger Emergency Oxygen Container Assembly Type III     | 32C15_0000-SERIES<br>33C15_0000-SERIES<br>34C15_0000-SERIES                                     | 01.03.1992 | 0   | Airbus  |
| 35-21-31 | CMM  | Passenger Emergency Oxygen Container Assembly Type III     | 3XC15/22_0001-0005-SERIES<br>33C15/22_0001-0005-SERIES<br>34C15/22_0001-0005-SERIES             | 01.01.2009 | 4   | Airbus  |
| 35-21-40 | CMM  | Passenger Emergency Oxygen Container Assembly Type II      | 22G_0000-SERIES<br>22G_0001-SERIES  | 01.08.2006 | 3   | Airbus  |
| 35-21-41 | CMM  | Passenger Emergency Oxygen Container Assembly Type I       | 12G_0000-SERIES<br>13G_0000-SERIES<br>14G_0000-SERIES   | 01.05.2008 | 2   | Airbus  |
| 35-21-42 | CMM  | Passenger Emergency Oxygen Container Assembly Type III     | 32G_0000-SERIES / 0001-SERIES<br>33G_0000-SERIES / 0001-SERIES<br>34G_0000-SERIES / 0001-SERIES | 01.12.2006 | 3   | Airbus  |
| 35-21-43 | CMM  | Passenger Emergency Oxygen Container Gaseous, Blinker Mask | 22G_2000-SERIES<br>22G_2001-SERIES<br>22G_2003-SERIES   | 01.10.2003 | 3   | LH-B777 |
| 35-21-44 | CMM  | Passenger Emergency Oxygen Container Assembly Type II      | 22G000-2002-SERIES  | 01.11.2001 | 0   | LH 747  |
| 35-21-45 | CMM  | Passenger Emergency Oxygen Container Gaseous               | 5XG00_0001/0002/0004  | 01.05.2006 | 2   | Airbus  |

| ATA Ref  | TYPE | Description  | Partnumber   | ISSUE      | REV | A/C    |
|----------|------|--|--|------------|-----|--------|
| 35-21-46 | CMM  | Passenger Emergency Oxygen Container Gaseous         | 6XG00_0001/0002/0004   | 01.05.2006 | 2   | Airbus |
| 35-21-48 | CMM  | Container Gaseous Oxygen Type II                     | 22G000-0006  | 01.07.2008 | 1   | Airbus |
| 35-21-49 | CMM  | Container Gaseous Oxygen Type III                    | 32G000-0006<br>33G000-0006<br>34G000-0006                                  | 01.02.2006 | 0   | Airbus |
| 35-21-50 | CMM  | Oxygen Generator Assembly                            | E712-SERIES<br>E717-SERIES<br>E722-SERIES                                  | 30.04.2001 | 0   | Boeing |
| 35-21-51 | CMM  | Container Gaseous Oxygen Type VIII                   | 82G00-0006<br>83G00-0006<br>84G00-0006                                     | 01.07.2008 | 1   | Airbus |
| 35-21-52 | CMM  | Container Gaseous Oxygen Type IX                     | 92G00-0006<br>93G00-0006<br>94G00-0006                                     | 01.02.2006 | 0   | Airbus |
| 35-21-53 | CMM  | Container Gaseous Oxygen Type A                      | A2G000-0006<br>A3G000-0006<br>A4G000-0006                                  | 01.07.2008 | 1   | Airbus |
| 35-21-54 | CMM  | Container Gaseous Oxygen Type B                      | B3G000-0006<br>B4G000-0006   | 01.09.2006 | 0   | Airbus |
| 35-21-55 | ACMM | Oxygen Therapeutic Panel                             | 80G00T000XX0006<br>90G00T000XX0006<br>A0G00T000XX0006                      | 01.02.2008 | 0   | Airbus |
| 35-22-10 | CMM  | Passenger Emergency Oxygen Container Assembly Type I | 12C22_0000/0003-SERIES<br>13C22_0000/0003-SERIES<br>14C22_0000/0003-SERIES | 01.05.1999 | 1   | Airbus |

| ATA Ref  | TYPE | Description  | Partnumber             | ISSUE      | REV | A/C            |
|----------|------|--|------------------------|------------|-----|----------------|
| 35-22-20 | CMM  | Passenger Emergency Oxygen Container Assembly Type II  | 22C15_0001-0005-SERIES | 01.05.2008 | 5   | Airbus         |
|          |      |  | 22C22_0001-0005-SERIES |            |     |                |
| 35-22-21 | CMM  | Passenger Emergency Oxygen Container 28V Latch         | 22C15_1000-SERIES      | 01.08.1999 | 0   | Tupolev        |
|          |      |  | 22C22_1000-SERIES      |            |     |                |
| 35-22-22 | CMM  | Passenger Emergency Oxygen Container Assembly Type II  | 22C15_1001-SERIES      |            | 0   | Deleted BAE146 |
|          |      |  | 22C22_1001-SERIES      |            |     |                |
| 35-22-23 | CMM  | Passenger Emergency Oxygen Container Assembly Type II  | 22C15-2006-SERIES      | 01.07.2008 | 0   | Airbus         |
| 35-22-24 | CMM  | Passenger Emergency Oxygen Container Assembly Type I   | 22C36-0005-SERIES      | 01.03.2009 | 0   | Airbus         |
| 35-22-30 | CMM  | Passenger Emergency Oxygen Container Assembly Type III | 32C22_0000-SERIES      | 01.11.1992 | 0   | Airbus         |
|          |      |  | 33C22_0000-SERIES      |            |     |                |
|          |      |  | 34C22_0000-SERIES      |            |     |                |
| 35-23-10 | ACMM | Switch, Pressurisation                                 | E62837-00              | 01.08.2001 | 1   | LH-B737        |
| 35-23-11 | ACMM | Valve, Bleed/Vent                                      | E62840-00              | 01.08.2001 | 1   | LH-B737        |
| 35-23-12 | ACMM | Compensator, Thermal                                   | E62802-00              | 01.03.2001 | 0   | LH-B737        |
| 35-23-13 | ACMM | Test, Port   | E69013                 | 01.08.2001 | 1   | LH-B737        |

| ATA Ref  | TYPE | Description                   | Partnumber                          | ISSUE      | REV | A/C            |
|----------|------|-------------------------------|-------------------------------------|------------|-----|----------------|
| 35-23-14 | CMM  | Signal Averaging Unit         | E62815                              | 01.04.2001 | 0   | LH-B737        |
| 35-23-15 | ACMM | Filling Port - Oxygen         | E62375-00<br>E62910-00              | 01.03.2005 | 1   | Airbus         |
| 35-23-16 | ACMM | Indicator-Fill Panel          | E62378-00<br>E62911-00              | 01.03.2005 | 1   | Airbus         |
| 35-23-17 | ACMM | Transducer Temperature        | E62376-00<br>E62908-00              | 01.03.2005 | 1   | Airbus         |
| 35-23-18 | ACMM | Indicator Overboard Discharge | E62379-00<br>E62909-00              | 01.03.2005 | 1   | Airbus         |
| 35-23-19 | CMM  | Shut Off Valve, Electrical    | E62380-00<br>E62836-00<br>E62916-00 | 01.07.2005 | 2   | Airbus/LH-B737 |
| 35-23-20 | ACMM | Check Valve                   | E62381-00<br>E62835-00              | 10.11.2003 | 1   | Airbus         |
| 35-23-21 | ACMM | Pressure Switch - Oxygen      | E62383-00<br>E62913-00<br>E62914-00 | 01.03.2005 | 1   | Airbus         |
| 35-23-22 | ACMM | Test Port Oxygen              | E62384-00<br>E62912-00              | 01.03.2005 | 1   | Airbus         |
| 35-23-23 | ACMM | Switch - Delta Pressure       | E62386-00<br>E62915-00              | 01.03.2005 | 2   | Airbus         |
| 35-23-24 | ACMM | Valve, Bleed / Vent           | E62387-00<br>E62918-00              | 01.03.2005 | 1   | Airbus         |

| ATA Ref           | TYPE | Description  | Partnumber        | ISSUE      | REV | A/C     |
|-------------------|------|--|-------------------|------------|-----|---------|
| 35-23-25          | ACMM | Tube, Flexible (Hydraflow)   | 38301-SERIES      |            | 0   | Deleted |
| 35-23-26          | ACMM | Tube Flexible (Titeflex)   | A22-SERIES        |            | 0   | Deleted |
| 35-23-27          | ACMM | Check Valve  | E62835-00         |            | 0   | Deleted |
| 35-23-28          | CMM  | Valve, Shutoff, Elec   | E62916-SERIES     |            | 0   | Deleted |
| GEM E69026-35-001 | GEM  | Flow Tester-Reg./Distri. Device                                      | E69026-SERIES     | 01.08.2005 | 0   | Airbus  |
| SB 1XC15-35-001   | SB   | PAX Type I Modification from 15 to 22 Minutes                        | 1XC15-0004-SERIES | 08.08.2004 | 0   | Airbus  |
| SB 1XCXX-35-001   | SB   | Passenger Emergency Oxygen Container Assembly Type I                 | 1XCXX-SERIES      | 05.05.1995 | 0   | Airbus  |
| SB 1XCXX-35-002   | SB   | Passenger Emergency Oxygen Container Assembly Type I,Mask Conversion | 1XCXX-SERIES      | 15.11.2004 | 0   | Airbus  |
| SB 22C15-35-001   | SB   | Passenger Emergency Oxygen Container Assembly Type II                | 22C15_0000-SERIES | 03.03.1994 | 0   | Airbus  |
| SB 22C15-35-002   | SB   | PAX Type I Modification from 15 to 22 Minutes                        | 22C15-0004-SERIES | 14.09.2004 | 0   | Airbus  |

| ATA Ref             | TYPE | Description   | Partnumber        | ISSUE      | REV | A/C    |
|---------------------|------|---|-------------------|------------|-----|--------|
| SB 2XG00-35-001     | SB   | Passenger Emergency Oxygen Container Assembly, Gaseous            | 22G0003C0442003   | 19.11.2004 | 0   | BBJ    |
|                     |      |   | 23G0003C0442003   |            |     |        |
| SB 2XG00-35-002     | SB   | Passenger Emergency Oxygen Container Assembly, Gaseous            | 22G0003C0442004   | 19.11.2004 | 0   | BBJ    |
|                     |      |   | 23G0003C0442004   |            |     |        |
| SB 3XC15-35-001     | SB   | PAX Type I Modification from 15 to 22 Minutes                     | 3XC15-0004-SERIES | 14.09.2004 | 0   | AIB    |
| SB 3XCXX-35-001     | SB   | Passenger Emergency Oxygen Container Assembly Type III            | 3XCXX-SERIES      | 22.08.1995 | 0   | Airbus |
| SB 402E300XX-35-001 | SB   | Replacement of Oxygen Door Springs                                | 402E30025-000     | 11.04.2001 | 3   | B717   |
|                     |      |   | 402E30025-001     |            |     |        |
|                     |      |   | 402E30035-000     |            |     |        |
| SB 630XXXX-35-001   | SB   | Oxygen Container and Oxygen Generator Assembly                    | 630XXXX           | 25.11.1998 | 1   | Airbus |
| SB E28180-35-001    | SB   | Protective Breathing Equipment OXYCREW                            | E28180            | 29.01.1990 | 0   | ALL    |
| SB E28180-35-002    | SB   | Protective Breathing Equipment                                    | E28180            | 15.01.1999 | 0   | ALL    |
| SB E28250-35-001    | SB   | OXYCREW Training Equipment  | E28250            | 15.06.1991 | 0   | ALL    |
| SB E62800-00-35-001 | SB   | Bracket to strenghten the Hand Valve/Reducer Structural Interface | E62800            | 22.02.2002 | 0   | BBJ    |

# Technical Publication Index



| ATA Ref               | TYPE | Description   | Partnumber                   | ISSUE      | REV | A/C    |
|-----------------------|------|---|------------------------------|------------|-----|--------|
| SB E62900-00-35-001   | SB   | Bracket to strenghten the Hand Valve/Reducer Structural Interface | E62900                       | 22.02.2002 | 0   | BBJ    |
| SB E62900-00-35-002   | SB   | Recall of Therapeutic Reducer                                     | E62900                       | 12.03.2002 | 0   | BBJ    |
| SB E69006-35-001      | SB   | Quantity Calculation and Control Unit QCCU                        | E69006                       | 01.03.1996 | 0   | Airbus |
| SB E75010-35-001      | SB   | FWD Oxygen Box, Generator Spring Installation                     | E75010-00                    | 15.10.1999 | 0   | B717   |
| SB S417T401-01-35-001 | SB   | Oxygen Generator Assembly   | E712-SERIES<br>E722-Series   | 15.04.1997 | 1   | Boeing |
| SB XXG00-35-002       | SB   | Passenger Emergency Oxygen Container Assembly, Gaseous            | 1XG00<br>2XG00<br>3XG00      | 15.03.2002 | 0   | Airbus |
| SB XXG00-35-003       | SB   | Passenger Emergency Oxygen Container Assembly, Gaseous            | 5XG00-SERIES<br>6XG00-SERIES | 14.07.2003 | 0   | Airbus |
| SB XXG00-35-004       | SB   | Passenger Emergency Oxygen Container Assembly, Gaseous            | XXG00-SERIES                 | 25.08.2004 | 2   | Airbus |
| SB XXG00-35-005       | SB   | Passenger Emergency Oxygen Container Assembly, Gaseous            | XXG00-SERIES                 | 25.08.2004 | 1   | Airbus |
| SIL E28180-35-001     | SIL  | Protective Breathing Equipment OXYCREW                            | E28180                       | 12.07.1990 | 0   | ALL    |

| ATA Ref           | TYPE | Description  | Partnumber  | ISSUE      | REV | A/C    |
|-------------------|------|--|---|------------|-----|--------|
| SIL E28180-35-002 | SIL  | Protective Breathing Equipment<br>OXYCREW  | E28180  | 11.01.1991 | 0   | ALL    |
| SIL E28180-35-003 | SIL  | Protective Breathing Equipment<br>OXYCREW  | E28180  | 18.05.1994 | 0   | ALL    |
| SIL E28180-35-004 | SIL  | Protective Breathing Equipment<br>OXYCREW  | E28180  | 02.04.1996 | 0   | ALL    |
| SIL E28180-35-005 | SIL  | Protective Breathing Equipment<br>OXYCREW  | E28180  | 05.07.1996 | 0   | ALL    |
| SIL E63XXX-35-001 | SIL  | Safe Removal of Safety Pind and<br>Warning Flag Assembly                         | E63XXX-SERIES   | 28.06.1999 | 2   | Airbus |
| SIL XXXXX-35-001  | SIL  | Mask Stowage Instruction   | XXXXX   | 06.10.1994 | 0   | Airbus |
| SIL XXXXX-35-002  | SIL  | Foam Pad Inspection Instruction  | XXXXX   | 07.02.2001 | 0   | Airbus |
| SIL XXXXX-35-003  | SIL  | Mask, Tube, Lanyard and Pull Flag<br>Stowage                                     | 13CXXY2F2XX0004<br>13C22Y4G4XX0004<br>33CXX04H2XX0004 | 21.03.2001 | 0   | Airbus |
| SIL XXXXX-35-004  | SIL  | Modification of Electrical Latch<br>Direction and Lable Rouging                  | XXXXX   | 29.05.2001 | 1   | Airbus |
| SIL XXXXX-35-05   | SIL  | Oxygen Generator Chemical, Expiry<br>Date, Disposal and Shipping<br>Instructions | XXXXX   | 29.04.2005 | 0   | ALL    |